

NANOBOT

ASSEMBLY TUTORIAL


Assemble steps:

1. Assemble the load-bearing wheel
(first install the M4*50 long screw into the load-bearing wheel)



Lock the other side with M4 nut






NANOBOT

ASSEMBLY TUTORIAL

2.Put the gasket on the bracket and put the bearing wheel into the hole of the bracket



Leave some space between this screw and the wheel, not too tight, or the wheel won't turn



NANOBOT

ASSEMBLY TUTORIAL

The other end is also fitted with a gasket, which is also locked with the M4 nut. Be careful not to tighten the bearing wheel too tightly.





NANOBOT

ASSEMBLY TUTORIAL

3.Put the motor into the bracket and tighten it with 3 M3*6 flat head screws.






NANOBOT

ASSEMBLY TUTORIAL

4. Install the driving wheel: the coupling is set into the driving wheel, the other end of the M3*8 hexagonal socket screw is set into the driving wheel with an inner hexagonal wrench, and the coupling is locked.





NANOBOT

ASSEMBLY TUTORIAL

5. Attach drive wheel to motor and tighten with jacking wire.



Please note: the hole in the coupling must be aligned with the flat end of the motor shaft, so that the coupling is stuck to the position indicated by the arrow.





NANOBOT

ASSEMBLY TUTORIAL

6.First dismantle the crawler and remove the extra parts





NANOBOT

ASSEMBLY TUTORIAL

7. Measure the required track length





NANOBOT

ASSEMBLY TUTORIAL

8. Insert the track needle into the track with the aid of a tool






NANOBOT

ASSEMBLY TUTORIAL

Successful assembly






NANOBOT

ASSEMBLY TUTORIAL

9. Fix 4 50CM copper columns on the chassis with screws






NANOBOT

ASSEMBLY TUTORIAL

10. Fix the battery box on the chassis with M3 nut and M3*8 screws







NANOBOT

ASSEMBLY TUTORIAL

11. Fasten the acrylic chassis with 4 screws







NANOBOT

ASSEMBLY TUTORIAL

12. Fix the 15cm copper column to the acrylic plate with screws







NANOBOT

ASSEMBLY TUTORIAL

13. Plug the RF-Nano into the extension board, and then fix the extension board with four screws.







NANOBOT

ASSEMBLY TUTORIAL

14. Fix the SG90 steering gear on the acrylic plate with M2 screw and nut, and connect the wire to the expansion plate





NANOBOT

ASSEMBLY TUTORIAL

15. Assemble ultrasonic wave

① prepare material



② Fix the ultrasonic wave to the bracket by M1.6 screws and nuts





NANOBOT

ASSEMBLY TUTORIAL

③ Secure the bracket with the M2 screw







NANOBOT

ASSEMBLY TUTORIAL

④ Fix the bracket and the white material with the M3 self-tapping screw








NANOBOT

ASSEMBLY TUTORIAL

16. Fix the ultrasonic wave to the steering gear.







NANOBOT

ASSEMBLY TUTORIAL

17. Connect the ultrasonic wave to the expansion plate with 4PIN terminal wire






NANOBOT

ASSEMBLY TUTORIAL

18. Plug the HC-06 Bluetooth module into the expansion board





NANOBOT

ASSEMBLY TUTORIAL

19. Fix the two infrared obstacle avoidance modules to the extension board with M3 screws, and connect them to the board with wires. Finally, plug the wires of the two motors into the fixed interface.

