


Filament Dry Box User Manual 400



Operation Guide

- 1. Turn on power: Plug the power cord into socket and connect the dry box to power supply. When the screen shows OFF, the dry box is in a standby state.
- 2. Put in Filament: Put filament into the dry box, drag it from the hole, close top cover, turn the knob clockwise to adjust to the working time by 2/4/8 hours. The dry box will start working.

Into the working state.

Process Memory: If there is power failure during the drying process, it will automatically memorize and display the drying time before the power failure when it's restarted.

Precautions for safe use

- 1. Do not use the product when the power cord and socket are damaged or in contact with water.
- 2. When using the heating function, do not touch water and other flammable materials.
- 3. When not using this product for a long time, please cut off the power to avoid sudden fire.
- 4. Do not use this product in a humid environment.
- 5. Do not let children play with this product.
- 6. If this product is malfunctioning, please turn off the power first and pull out the power plug from the socket. Do not continue to use it, and contact our company's after–sales service personnel. Do not replace non–original parts or disassemble and repair by yourself.

Product Parameter

Model	DB-01
Product Dimension	233*266*99mm
Weight	
Color	Transparent, White
Material	PPS, ABS, PC
Craft	Polishing & Sun Pattern
Connector	AC100-240V Power Connector
Temperature Range	50°C±10°C
Time Range	OFF/2/4/8 hours
Screen	Digital Tube (4 digits)
Operation	Knob
Power	120W
Power Supply	Built-in
Input Voltage	AC 100-240V 50/60Hz
Filament Diameter	1.75mm
Spool Supported	1kg Filament Spool

Users should comply with the laws and regulations of the corresponding countries and regions where the equipment is located (used) and ethical principles, fulfill safety obligations, and strictly prohibit the use of our products or equipment for any illegal purposes. Creality will not be responsible for any violators' legal liability under any circumstance.



SHENZHEN CREALITY 3D TECHNOLOGY CO., LTD.

Add: 18F, JinXiuHongDu Building, Meilong Blvd., Longhua Dist., Shenzhen, China 518131 Official Website: www.creality.com

Tel: +86 755-8523 4565

E-mail: info@creality.com cs@creality.com